

FIVE ZERO CMM ELEVATION OF GROUND SURROUNDING STATION ONE FIVE ZERO
IS APPROXIMATELY PLUS FIVE FEET PD BEDROCK UNDER STATION IS AT ELEVATION
THREE PNT THREE FEET PD BOTTOM OF SLAB IS ELEVATION FIVE PNT THREE
FEET PD BECAUSE OF POSSIBILITY OF UNDERCUTTING OF UNSTABLE MATERIAL
WHICH HAS BEEN DISTURBED IN REMOVING OLD SANSTONE STATION AND
EXCAVATING FOR PIPE TO WELL UNDER HIGH TIDE AND STORM CONDITIONS
CMM WE HAVE APPROVED POURING TWO FEET PNT ZERO INCHES OF LEAN CONCRETE

TO GUARANTEE FOUNDATION STABILITY

10/0 107 DEPARTMENT OF THE ROSE DASS REPAIRW

SINGLE REVIEW AUTHORISTS OF THE ROSE DASS REPAIRW

A STANIS GRIT T-23 90

REVIEWER (ADD):

NAME: J.D. LABERT

DATE: 7/0 9/1944 G. CLASSRIPD INFO BRACKETED